


直纹滚花


2 x M4锁紧螺丝

5 x M4锁紧螺丝



12 x  $\phi 6.60$  完全贯穿  
 $\square \phi 11 \nabla 6.80$

10 x M6 - 6H  $\nabla 12$   
 $\phi 5 \nabla 15$



PT80-100

北京派迪威仪器有限公司